LOTUS/WEST OWNERS SURVEY (FAILURE REPORTS)

The following paragraphs and chart appeared in the April 1972 issue of <u>Stress</u> <u>Cracks</u> under the authorship of then-Technical Committee Chairman, Tom Dill. No attempt has been made to update this survey since then because of the response problems mentioned by Mr. Dill. For those with further interest in this subject, the <u>Road & Track</u> Elan Owner Survey appeared in the April 1971 issue of <u>R & T</u>.

Inertia is readily overcome with a Lotus, but not so the human being, even the Lotus owners when asked to reply to an owner's survey. It's rather discouraging that <u>Road & Track</u> can get response from 70 individuals (which it called marginal in terms of sample size), while the largest owners club (us) can get a paltry 161

It would not have been worthwhile to analyze the data were it not that they seem representative of the myriad Elan owner's reports and complaints I have personally heard over beer and busted knucks. Of the Europa results it is not for me to comment, being relatively unfamiliar with the car's characteristics. Lotus Cortina owners had little to say (that's good, that's good!) They undoubtedly have interesting facts to relate. I have a sneaking hunch the car may be most reliable of all.

Ι

FAILURES REPORTED Elan

· · ·

Total Miles 380,000 Average Miles 31,600

£ .

1 6

)

Number I2 Models 164-69

1

6

% ' Owners Reporting	Pov Engine/ Cooling	ver Tra Transmission	in Differential	Electrical- Instruments	Body Cracks, Leaks	Chassis- Suspension
75-100%		Slave Cylinder				·
50-74%	Water Pump, Starter Drive	Clutch Master Cylinder		Generator Bearing,wiring, Switches	Electric Windows, various, '66 on	Rear Wheel Bearings, Motor Mounts
25-49%	Oil leaks Broken cam Broken generator bracket	Throw—out Bearing	Donuts, from jacking	Water temp Gauge	weather leaks, wind	
I-24%	Fuel blockage, Gen. pulley, Throttle cable Freeze plugs leak, out Carb.,Zenith only	Front U-joint Ist-2nd synchro assy.,shaft nut	Output shaft wear, break Pinion seal	Speedometer, Headlight vacuum syst., leaks, pots, Distributor adv.,Zenith	Fuel pump v. body Handbrake	Shocks, rear

Total Mile Average Mi		₩ ¹	Europa			umber 4 odels S2-'7I
75-100%	Overheating	Clutch cable		Battery, Wiring, Switches		
25-74%					Leaks, Door alignment	
I-24%	Fast idle, head gasket, throttle cable	Shift lever		Speedometer	Paint Stress Cracks	Rear hub, Shocks

.

00MC043

· ~

N

ě.