

<u>SUBJECT</u>	<u>ARTICLE No.</u>
<u>Body & Interior (BI)</u>	
Elan(26)	
Door Windows(Elan coupe & drophead)	17
Ventilating Interior of Elan	22
Europa(54)	
Repair of Europa Door Sag	56
Weathersealing Europa Engine Compartment	84
Plexiglas Headlight Covers	85
One Rusty Europa	86
General(00)	
Minor Fiberglass Repair	2
Concourse Primer	45
Refinishing Your Dashboard	51
<u>Engine (EN)</u>	
Elite(14)	
Coventry Climax Engine	3
Elan(26)	
Optional Camshafts for the TwinCam	10
TwinCam Noise(Timing Chain Adjustment)	11
Freeze-plug Fix	16
Installing Rear Freeze-plug in Elan Head	18
Removal of Elan Oil Pan	19
An End to Elan Oil Pressure Loss & Checking Valve to Piston Clearance	26
Ring Gear Replacement	52
Low Oil Pressure Signal	62
The TwinCam Tilt	92
Esprit(74)	
Esprit Tech Tips	102
General(00)	
Degreasing Cams	63
Installation of Reground Camshafts into the Lotus TwinCam	78
TwinCam Valve Stem Seals	79
Diagnosis of Inconsistent Idle Problems	93
Everything You Should Know About Timing Belts	106
<u>Electrical System (EL)</u>	
Elan(26)	
Headlight Vacuum Pot	5
Headlight Flashers	8

Electrical System (EL), continued

Elan(26)
 Dead Ball Bearings in Lucas Generator12
 Generator-to-Alternator Conversion13
 Starter44

Europa(54)
 110 Volt Power for the Europa57
 Converting Europa Reflectors into Lights60
 Internal Europa Radio Antenna61

General(00)
 A Light Matter50
 C-D Ignitions54
 Starter Problems and TwinCam Starter Rebuild75
 Let the Juices Flow88
 High Tension Lead - Shade Tree Static Timing103

Wheels, Tires & Suspension(WS)

Lotus 7(07)
 Eliminating Plowing24

Elan(26)
 Clunk in Differential20
 Konis for Your Elan25
 Tire Changing "Knock On" Wheel Bolts39

Cortina(28)
 Lowering Ride Height on the Cortina Mk. I & Mk. II .87

Europa(54)
 Play in Rear Wheels47
 Konis for Your Europa89
 Europa Toe-in for Front and Rear Wheels94
 Europa Brake Maintenance and Replacement97
 Europa Handbrake Adjustment Modifications98

General(00)
 Tire Code Sheet & Notes on Shocks Application32
 Wheel Bearings53
 Be A Winner: Check Your Brakes101

Drive Train (DT)

Elan(26)
 Final Drive, Rear Brakes 9
 Removal of Elan Differential Inner Stub Shafts34
 Donut Installation36

SUBJECTARTICLE No.Drive Train (DT), continued

Elan(26)

Pre '68 TwinCam Diaphragm Clutches & Clutch	
Slave Cylinder	40
When Tranny Pops Out of 2ND Gear	46
Fatigue (not Stress) Cracks	76
When Tranny Pops Out of 2ND Gear (Revisited)	77
Caution on Pressure Plate-Flywheel Capscrews	91

Europa(54)

Shift Lever, Shifting Bellcrank Unit, Throttle	
Return Spring	14
Europa Rear Suspension Checkout	74

Cooling Systems (CS)

Elan(26)

Heater Valve	4
Water Pump Replacement in TwinCam	21
Cooling the Elan	23
Water Temperature Gauge Conversion	30
Cooling Systems	64

Europa(54)

Thermostatic Radiator Fan, Throttle Cable	15
---	----

Fuel System (FU)

Elan(26)

Throttle Pedal & Cable Maintenance	6
The Ultimate Elan Gas Tank	99

Europa(54)

Europa Choke Assembly for Webers	59
Pre-TC Europa Gas Capacity Increased	69

General(00)

Understanding the Weber Carburetor, Part 1	38
Weber Carburetor, Part 2	41
Weber Carburetor, Conclusion	42
Weber Tuning Notes	48
Weber Carburetor Jet Guide	55
Fuel Systems	105

Miscellaneous (MC)

Elite(14)

Lotus Fourteen Introductory	1
Elite: 1973 Lotus Clinic Annual	68

Miscellaneous (MC), continued

Seven(07)	
1974 Lotus Clinic Annual	72
Elan(26)	
Troubleshooting a High-Mileage Elan	49
1973 Lotus Clinic Annual	65
1974 Lotus Clinic Annual	70
1975 Lotus Clinic Annual	80
Cortina(28)	
1973 Lotus Clinic Annual	68
Rebuilding the Girling Vacuum Brake Servo Unit	90
Europa(54)	
1973 Lotus Clinic Annual	66
1974 Lotus Clinic Annual	71
1975 Lotus Clinic Annual	81
Lotus Europa Service Hints - 1978	96
Europa TC(74)	
Lotus Europa TwinCam Parts Crossreference	83
'82 - '83 Europa Clinic	104
General(00)	
Where to Find Lotus Articles & Books on Lotus	29
Lotus Frame Repair	35
Higher Revs Cheaply	37
Lotus/West Owners Survey (Failure Reports)	43
Slalom Techniques	58
1973 Lotus Clinic Annual	67
1974 Lotus Clinic Annual	73
1975 Lotus Clinic Annual	82
How Well Does It Corner ?	95
Computing Speed From the Tachometer	100