

LOTUS WEST

INCORPORATED

CAR CLUB

POST OFFICE BOX 73972, LOS ANGELES, CALIFORNIA 90005

Car No.

Category

Article No.

--
00 - General

07 - Lotus 7

14 - Elite

26 - Elan

28 - Lotus Cortina

50 - Elan +2

54 - Europa

--
BI - Body & Interior

EN - Engine

DT - Drive Train

WS - Wheels, Tires, &
Suspension

EL - Electrical System

CS - Cooling System

FU - Fuel System

MC - Miscellaneous

- 14MC001 - Vol. 1, No. 1, (Lotus Fourteen) Introductory
- 00BI002 - Vol. 2, No. 1, Minor Fiberglass Repair
- 14EN003 - Coventry Climax Engines Ltd.
- 26CS004 - Heater Valve
- 26EL005 - Headlight Vacuum Pot
- 26FU006 - Throttle Pedal & Cable Maintenance
- 26FU007 - Air Filter
- 26EL008 - Headlight Flashers
- 26DT009 - Final Drive, Rear Brakes
- 26EN010 - Optional Camshafts on Twincams
- 26EN011 - Twincam Noise (Timing chain adjustment)
- 26EL012 - Dead Ball Bearing in Lucas Generator
- 00FU013 - Octane/Price Survey
- 54DT014 - Shift Lever, Shifting bell crank unit, Throttle return
spring
- 54CS015 - Thermostatic Radiator fan, Throttle cable
- 26EN016 - Freeze-plug fix
- 26BI017 - Door Windows (Elan coupe & Drophead)
- 26EN018 - Installing Rear Freeze-plug in Elan head
- 26EN019 - Removal of Elan Oil Pan
- 26DT020 - Clunk in Differential
- 26CS021 - Water pump replacement in Twincam
- 26BI022 - Ventilating interior of Elan
- 26CS023 - Cooling Elan with fan
- 07WS024 - Eliminating plowing
- 26WS025 - Konis for your Elan
- 26EN026 - An end to Elan oil pressure loss & checking valve to piston
clearance
- 00MC027 - Testing tires, cornering forces, recaps
- 00WS028 - Fire extinguishers
- 00MC029 - Where to find Lotus articles
- 26CS030 - Water temperature gauge conversion

54CS031 - Radiator Fan Repair
 00WS032 - Tire Code Sheet & Notes on Shocks Application
 33 - (Article Deleted)
 26DT034 - Removal of Elan Differential Inner Stub Shafts
 00MC035 - Lotus Frame Repair
 26DT036 - Donut Installation
 00MC037 - Higher Revs Cheaply
 00FU038 - Understanding the Weber Carburetor, Part 1
 26WS039 - Tire Changing "Knock On" Wheel Nuts & Mounting
 Mirrors
 26DT040 - Pre '68 TwinCam Diaphragm Clutches & Clutch
 Slave Cylinder
 00FU041 - Weber Carburetor, Part 2
 00FU042 - Weber Carburetor, Conclusion
 00MC043 - Lotus/West Owner Survey (Failure Reports)
 26EL044 - Starter Problems
 00BI045 - Concourse Primer
 00DT046 - When Tranny Pops Out of 2ND Gear
 54WS047 - Play in Rear Wheels
 00FU048 - Weber Tuning Notes
 26MC049 - Troubleshooting a High-Mileage Elan
 00EL050 - A Light Matter
 00BI051 - Refinishing Your Dashboard
 26EN052 - Ring Gear Replacement
 00WS053 - Wheel Bearings
 00EL054 - C-D Ignitions
 00FU055 - Weber Carburetor Jet Guide
 54BI056 - Repair of Europa Door Sag
 54EL057 - 110 Volt Power for the Europa
 00MC058 - Slalom Techniques
 54FU059 - Europa Choke Assembly for Webers
 54EL060 - Converting Europa Reflectors into Lights
 54EL061 - Internal Europa Radio Antenna
 00EL062 - Low Oil Pressure Signal
 00EN063 - Degreasing Cams
 26CS064 - Cooling Systems
 26MC065 - Elan: 1973 Lotus Clinic Annual
 54MC066 - Europa: 1973 Lotus Clinic Annual
 00MC067 - General Information: 1973 Lotus Clinic Annual
 14MC068 - Elite and Cortina: 1973 Lotus Clinic Annual
 28MC068
 54FU069 - Pre-TC Europa Gas Capacity Increased
 26MC070 - Elan: 1974 Lotus Clinic Annual
 54MC071 - Europa: 1974 Lotus Clinic Annual
 07MC072 - Lotus 7: 1974 Lotus Clinic Annual
 00MC073 - General Information: 1974 Lotus Clinic Annual
 54DT074 - Europa Rear Suspension Checkout
 00EL075 - Starter Problems & TwinCam Starter Rebuild
 26DT076 - Fatigue (not Stress) Cracks
 26DT077 - When Tranny Pops Out of 2ND Gear (Revisited)
 00EN078 - Installation of Reground Camshafts into the
 Lotus TwinCam
 00EN079 - TwinCam Valve Stem Seals
 26MC080 - Elan: 1975 Lotus Clinic Annual

54MC081 - Europa: 1975 Lotus Clinic Annual
00MC082 - General Informaion: 1975 Lotus Clinic Annual
74MC083 - Lotus Europa Twincam Parts Crossreference
54BI084 - Weathersealing Europa Engine Compartment
54BI085 - Plexiglas Europa Headlight Covers
54BI086 - One Rusty Europa
28WS087 - Lowering Ride Height on the Cortina Mk. I and
Mk. II
00EL088 - Let the Juices Flow
54WS089 - Konis for Your Europa
28MC090 - Rebuilding the Girling Vacuum Brake Servo Unit
26DT091 - Caution on Pressure Plate-Flywheel Capscrews
26EN092 - The Twincam Tilt
00EN093 - Diagnosis of Inconsistent Idle Problems
54WS094 - Europa Toe-In for Front and Rear Wheels
00MC095 - How Well Does It Corner?
54MC096 - Lotus Europa Service Hints - 1978
54WS097 - Europa Brake Maintenance and Replacement
54WS098 - Europa Handbrake Adjustment Modification
26FU099 - The Ultimate Elan Gas Tank
00MC100 - Computing Speed From the Tachometer
00WS101 - Be A Winner: Check Your Brakes
79EN102 - Esprit Tech Tips
00EL103 - High Tension Lead - Shade Tree Static Timing
74MC104 - '82 - '83 Europa Clinic
00FU105 - Fuel Systems
00EN106 - Everything You Should Know About Timing Belts